


POS.7
Mat=1.7131
HARDNESS:50±2HRC



Surface roughness selected range simplified symbol	dia symbol	REVISION	NAME	DATE	SIGN	SCALE	شركة سیمان داراب DARAB CEMENT CO	
$\sqrt{\text{---}}$ = Optional	\sim	OLD DRAWING NO	DATE	DRAWN: Sh.omidbaksh	90/12/08	1:1	WEIGHT	DARAB CEMENT CO
\sqrt{X} = $\sqrt{R 100}$	∇	HARDNESS		APPROVED: K Oladood.A	98/12/08	MATERIAL	Item No	SHEET
\sqrt{Y} = $\sqrt{R 25}$	$\nabla\nabla$	SIZE: A4	UNIT: mm	DESIGN		Quant.	Sheet No	7-8
\sqrt{Z} = $\sqrt{R 6.3}$	$\nabla\nabla\nabla$	TITLE: نقشه های مربوط به زنجیر ریکلایمر					DRAWING NO.	D.C.C-0729