



| Surface roughness selected range simplified symbol | dia symbol |
|--|------------------------|
| $\sqrt{\text{---}}$ = Optional | \sim |
| $\sqrt{X} = \sqrt{R_z 100}$ | ∇ |
| $\sqrt{Y} = \sqrt{R_z 25}$ | $\nabla \nabla$ |
| $\sqrt{Z} = \sqrt{R_z 6.3}$ | $\nabla \nabla \nabla$ |

| REVISION | | NAME | DATE | SIGN | SCALE |
|---|-------------|---------------------------|----------|------|-------------|
| OLD DRAWING NO | DATE | DRAWN: Sh. omtadbakhs | 90/12/06 | | 1:1 |
| HARDNESS | | CHECKED: | | | WEIGHT |
| SIZE: A4 | UNIT: mm | APPROVED: K. Oladzad A | 90/12/06 | | MATERIAL |
| TITLE: نقشه های مربوط به زنجیر ریکلابر | | | | | Quant. - |

| | | | | |
|-------------------------------------|--|----------------|---|-------|
| شرکت سیمان داراب DARAB CEMENT CO | | Item No: | - | SHEET |
| | | Sheet No: | - | |
| DRAWING NO. | | Parts list No: | - | 1-8 |
| D.C.C-0729 | | | | |